# CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company
1400 E. Havens
P.O. Box 754
Kokomo, IN 46903-0754
Attn: Ronda S. Yeakley

Order #: 98-02-006
Date: 02/05/98 07:42
Work ID: Effluent Water Composite
Date Received: 02/02/98
Date Completed: 02/04/98

Purchase Order: 206941
Invoice Number:

Client Code: MILBANK_MFG

## SAMPLE IDENTIFICATION

| Sample Number | Sample Description | Sample Number | Sample Description |
|---|---|---|---|
| 01 | Effluent Composite | | |

This report may not be reproduced except in full, without the written approval of the laboratory. All results relate only to the items tested.
This report contains a total number of pages: 02

_____
Certified By

---

*Astbury Water Technology, Inc.*

ENVIRONMENTAL SERVICES
5933 WEST 71ST STREET    INDIANAPOLIS, INDIANA 46278
A Member of THE ASTBURY GROUP

PHONE (317) 290-1471
FAX (317) 290-1670

Sample: 01AW   Effluent Composite          Collected: 01/30/98  Category: WATER

| Test Description | Result | Limit | Units | Analyzed | By |
|---|---|---|---|---|---|
| Zinc, ICAPES | 1.380 | 0.010 | mg/L | 02/04/98 | JAR |

AWT

# ESG Laboratories

5933 West 71st Street • Indianapolis, IN 46278

Phone (317) 290-1471 • Fax (317) 290-1670

## CHAIN OF CUSTODY RECORD

FEB 26 1998

| Client Name: Milbant Mfg | ESG Work Order #: 7802006 |
|---|---|

Project No: 

Project Name:

Sampler(s) Signature: Kurt E. Cales

**Preservation Codes:**
A = Acid
B = Base
C = Cool 4°

Filtered (Y or N)

Preserv. Code

Analyses: 3

| Stat.No | DATE | TIME | COMP | GRAB | STATION LOCATION ID | Total Number of Containers | | | | | | | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | 1-30-98 | 7:30 | x | | Effluent Pit | 1 | 1 | | | | | | | | | |

| Relinquished By: Kurt E. Cales | Date / Time 2-2-98 10:00 | Received By: | Date / Time 2/2/98 10:45 |
|---|---|---|---|
| Relinquished By: | Date / Time | Received By: | Date / Time |
| Relinquished By: | Date / Time | Received By: | Date / Time |

**Additional Information:**

Turn Around Time: Normal ☐ Rush ☐ Report Due: _____

Are samples suspected to be: Flammable ☐ Corrosive ☐ Toxic ☐

Were samples received intact and properly preserved? Yes ☐ No ☐

Temp. Blank _____ °C

kmg\newcoc\xls

MIL0004953